--58. The water spa for bathing of claim 54, wherein an error message is displayed on the control panel in alphanumeric characters when lack of water flow is detected by the second sensor.

## REMARKS

By this paper, original claims 1-34 have been canceled and new claims 35-58 added. Claims 35-58 are pending.

In addition, certain amendments were made to the specification for clarification to correct errors. It is believed that no new matter has been added.

Respectfully submitted,

FULWIDER PATTON LEE & UTECHT, LLP

John V. Hanley

Registration No. 38,171

JVH:kst Howard Hughes Center 6060 Center Drive, Tenth Floor Los Angeles, CA 90045 Tel. No. (310) 824-5555 Fax No. (310) 824-9696 #192403